

Type of Bulletin:

Product Change Bulletin

Date Of Bulletin:

4-29-2011

This Bulletin Superseded Bulletin(s):

None

Models Affected:

GTX

Machine Symptoms:

Rear tires lose traction when wet



Old 290-6180



New 250-6180

Scope of Bulletin:

The new moderate durometer poly tire offers a better balance of traction and reduced rolling resistance. This will lower the current load on the traction motor and thus reduce internal wear on the motor. The new tread pattern is designed for maximum traction and also reduced vibration.

Materials Required:

250-6180

Inspection:

Diamond pattern is the old tire.

Correction:

This is a direct replacement of the old tire. Prop machine up with a car jack and use a impact wrench to loosen and take off the lug nuts. Replace with new tire and tighten lug nuts.