

**Type of Bulletin:**

Product Change Bulletin

**Date Of Bulletin:**

5-29-2011

**This Bulletin Superseded Bulletin(s):**

None

**Models Affected:**

XR

**Machine Symptoms:**

Rear tires lose traction when wet



**Old 370-6180**

**New 370-6186**

**Scope of Bulletin:**

The new moderate durometer poly tire offers a better balance of traction and reduced rolling resistance. This will lower the current load on the traction motor and thus reduce internal wear on the motor. The new tread pattern is designed for maximum traction and also reduced vibration.

**Materials Required:**

370-6186

**Inspection:**

Square pattern is the old tire.

**Correction:**

This is a direct replacement of the old tire. Prop machine up with a car jack and use a impact wrench to loosen and take off the lug nuts. Replace with new tire and tighten lug nuts.