

DATE OF BULLETIN:

10-9-2017

THIS BULLETIN SUPERSEDED BULLETIN(S):

None

MODELS AFFECTED:

SPORT	CARBON	HERO
PRO	GTX	XR
VR	200	270
255		

Excluded Models:

RECON	MICROMINI	GT
-------	-----------	----

MACHINE SYMPTOMS:

None

SCOPE OF BULLETIN:

New Charger Used For:

- Onboard Chargers
- AGM Batteries
- International AC Voltage
- California CEC Specifications

MATERIALS REQUIRED:

None

REVISIONS:

All machines include new yellow steel cord wrap with Delta Q Chargers to easily secure cords while machine is in operation.



Yellow Inhibit Light Activated on Walk Behinds

A close-up of a machine dashboard. On the left, there is a yellow emergency stop button with a red center and the words "EMERGENCY STOP" around it. Below the button is a yellow light that is illuminated. To the right of the light is a black LCD screen. Above the screen, it says "MADE IN USA 1-800-450-9824". There are various other controls and buttons on the dashboard, including a blue button and a red button.

Walk Behinds with an Onboard Delta Q Charger feature an internal inhibit switch and a new light on the dashboard of the CC to illuminate when the equipment won't move due to charging.

Inhibit Error Code on Riders

A close-up of a machine LCD screen. The screen is green and displays an error code "1E03" in the center, which is circled by a dashed yellow line. To the right of the error code is a warning triangle icon. On the left side of the screen, there are three vertical bars representing battery levels.

Riders with an Onboard Delta Q Charger do not feature a new light, but instead trigger an inhibit error code on the LCD when operator is charging unit and trying to drive.