

Type of Bulletin:

Product Change Bulletin

Date Of Bulletin:

01-01-2010

This Bulletin Superseded Bulletin(s):

None

Models Affected:

All

Machine Symptoms:

Battery cables are corroded, causing intermittent power or charging problems

Scope of Bulletin:

We changed the ends that get crimped onto the ends of our battery cables to help in the prevention of the wires becoming corroded and thus causing them to not function. This is not a prevention to corrosion, proper steps should still be taken to keep the battery terminals and cable ends clean and protected with corrosion prevention spray. But the new closed ends on cables helps prevent the corrosion from getting into the wire.

Materials Required:


New direct cable replacement

Inspection:

Check over the battery cables to see if corrosion has affected any wires

Correction:

Cables from the manufacturer are a direct replacement to the cables already on the machine. Simply take out the old wires and replace with new.



Result of old