

**Type of Bulletin:**

Product Change Bulletin

**Date Of Bulletin:**

03-15-2011

**This Bulletin Superseded Bulletin(s):**

None

**Models Affected:**

Red painted machines

**Machine Symptoms:**

Rough feeling paint, with flat finish



**Scope of Bulletin:**

New red paint is smoother and easier to clean. It has 15% gloss, which is the minimum we can get with the crinkle look, so its more susceptible to surface scratches, and care should be taken.

**Materials Required:**

None

**Inspection:**

Rough feeling paint, with flat finish

**Correction:**

No action needs to be taken, just a heads up on the new paint.



**Old**