

Type of Bulletin:

Product Change Bulletin

Date Of Bulletin:

03-20-2011

This Bulletin Superseded Bulletin(s):


None

Models Affected:

MiniMag, Magnum, GTX, XR

Machine Symptoms:

Warping or bending of the recovery tank lid



Scope of Bulletin:

The changes made to the recovery tank lid are not only being tinted but it has a higher temperature resistance (270F vs 170F with clear lid). Also the tank lid gaskets have improved adhesion and the lids have more surface area for the gaskets to attach to.

Materials Required:

190-1410D

Inspection:

Warped clear recovery tank lid, lid is not sealing.

Correction:

This is a direct replacement of the clear plastic lid. Remove the 2 screws holding the recovery lid to the metal tank lid and replace with new lid.