

Type of Bulletin:

Product Change Bulletin

Date Of Bulletin:

04-23-2011

This Bulletin Superseded Bulletin(s):

None

Models Affected:

MiniMag

Machine Symptoms:

Solid tires have traction loss

**Scope of Bulletin:**

We decided to go with a different tread pattern and material to improve traction on various floor types. The improved tread pattern allows more gripping power even on wet floors. Also the grey tire is an aesthetic improvement.

Materials Required:

170-6180

Inspection:

If the machine has a rounded black solid tire with diamond pattern, or solid grey tire with no pattern.

Correction:

This is a direct replacement of the old solid tire. Prop machine up on a wooden block or something that will support the weight of the machine from the frame. Take off the 4 nylocks holding the wheel on and replace with new solid tire.