

**Type of Bulletin:**

Product Change Bulletin

**Date Of Bulletin:**

6-21-2011

**This Bulletin Superseded Bulletin(s):**


None

**Models Affected:**

Magnum

**Machine Symptoms:**

Solid tires have traction loss



**Scope of Bulletin:**

We decided to go with a different tread pattern and material to improve traction on various floor types. The improved tread pattern allows more gripping power even on wet floors. Also the grey tire is an aesthetic improvement.

**Materials Required:**

253-6197D – Qty. 2

**Inspection:**

Black or grey metal rim tire

**Correction:**

Prop the machine up on a wooden block or something that can support the weight of the machine on its frame. Remove the nuts holding the tire on, knot out the studs from the transaxle and replace with the longer studs. Make sure the bushings are installed on the wheel opposite the transaxle. Slide wheel onto studs, add the Nylocks and tighten.