

Type of Bulletin:

Product Change Bulletin

Date Of Bulletin:

3-11-2011

This Bulletin Superseded Bulletin(s):

None

Models Affected:

MicroMag, MiniMag, Magnum, GTX,
XR

Machine Symptoms:

Foam causing the vacuum motor to be shut off to soon.

Scope of Bulletin:

We found that some machines in some applications were making to much foam in the recovery tank causing the vacuum motor to be shut off prematurely. This change allows the vac shut off float bracket to be moved up or down to achieve the correct setting.

Materials Required:

Updated baffle (refer to machines part book to find part number)

370-1122 Ball float holder

H-74419 (2)

H-71013 (2)

H-70860 (2)

Philips head screw driver

7/16" wrench or socket

Inspection:

A solid, one piece baffle without the adjustment slots is the old part.

Correction:

This is a direct replacement of the old part.

