

DATE OF BULLETIN:

08-22-2011

THIS BULLETIN SUPERSEDED BULLETIN(S):

None

MODELS AFFECTED:

Micro & MicroMag with foot pedal

SERIAL NUMBER INFORMATION:

Change was made in production beginning with Serial No. 61835

MACHINE SYMPTOMS:

Difficult Scrub Deck Up/Down via foot pedal

SCOPE OF BULLETIN:

Rarely in business have we found such unanimous support for a change on a machine, but such agreement does make the decision all the easier. The foot pedal to raise and lower the scrub deck on the newly introduced MicroMag was negatively received by both sales people and customers. So starting immediately, all MicroMags will come standard with the actuator at no extra charge, which had been a \$195 option.

MATERIALS REQUIRED:

To help dealers and customers who already have machines in the field, we'll provide an update kit (**Kit#: K-621** which includes parts only) to retrofit the actuator. We have performed the installation on a number of units here to measure the time at 2 - 3 hours and confirm the accuracy of the instructions. If this is not possible, then we also have a more easily installed "guide" that can be installed in only 5 minutes. This **Kit #K-622** helps the operator determine when the deck is UP or DOWN and how best to move the foot pedal.

INSPECTION:

N/A

CORRECTION:

Install either Kit#K-621 or K-622.

