

FACTORY CAT

DATE OF BULLETIN:

1-29-2014

THIS BULLETIN SUPERSEDED BULLETIN(S):

None

MODELS AFFECTED:

FactoryCat 34 Floor Sweepers

MACHINE SYMPTOMS:

Uneven traction and wheels out of round.

SCOPE OF BULLETIN:

To inform about the new standard Control sticker for Walk Behind Sweeper Machines that begin on February 1st, 2014.

MATERIALS REQUIRED:

To update old machine tires to current specifications use the part numbers listed below.

FACTORYCAT 34: Part # 4-618095 - \$48.28

REVISIONS:

- **FACTORYCAT 34 Wheels** - 10" (25.4cm) × 2.5" (6.35cm)

PCB-629



You will notice that in the 2014 Updated Pricing the Heavy Duty Package has gone away as there is only one size wheel now. Now only the HD Bumper needs to be added when purchasing.

• Control Sticker



New sticker shows where certain control options will be to better aid in operation:

Power Switch: Downward Position - OFF, Middle Position - Main Broom Only, Top Position - Main Broom and Side Broom.

Key Switch: Optional area for if customer wants a Key Switch to prevent unauthorized machine usage.

Recharge Counter: Displays total amount of recharge cycles.

Side Broom Speed Control: Optional Area if customer wants the ability to speed up and slow down Side Broom.