

DATE OF BULLETIN:

8-30-2017

THIS BULLETIN SUPERSEDED BULLETIN(S):

PCB-631 & PCB-632

MODELS AFFECTED:

MICRO-HD PILOT-HD
MINI-HD GTX (Standard Two-Tank Assembly Only)
MAG-HD XR (Standard Two-Tank Assembly Only)
Retired Models
PILOT

MACHINE SYMPTOMS:

Chipping of powder coating. Drain Saver falling inside of recovery tank.

SCOPE OF BULLETIN:

Rider Scrubbers switched over to Corrosion Resistant Yellow Poly and our MINI-HD switched over to Yellow Poly vs Black Poly Drain Saver. Other walk behinds will follow at a future date.

MATERIALS REQUIRED:

PILOT-HD / GTX Part #: 600-8915 (LIST \$56.40)
XR Part #: 700-8915 (LIST \$56.40)
Walk Behind Yellow Poly Basket Part #: 264-8915D (LIST \$83.36)

REVISIONS:

On August 1st, 2017 the Drain Saver Basket on our Rider Scrubbers switched from Powder-Coated Steel to Corrosion Resistant Yellow Poly. The MINI-HD switched to a Yellow Poly for increased visibility. The other walk behinds will follow at a later date.

