



### DATE OF THE BULLETIN:

December 6th, 2019

# THIS BULLETIN SPERSEDED BULLETIN(S):

None

### **MODELS AFFECTED:**

150 MicroMag Series 164 MicroMini Series 155 MicroHD Series

### **MACHINE SYMPTOMS:**

None

## **SCOPE OF BULLETIN:**

Changing tire tread

# **MATERIALS REQUIRED:**

None

#### **REVISIONS:**

We now are no longer cutting tread patterns on above mentioned Walk Behind scrubber models including Traction and Pad Assist.





(Old Tread on left hand – No Tread on right hand)

