

DATE OF THE BULLETIN: May 4th, 2020

THIS BULLETIN SPERSEDED BULLETIN(S): None

MODELS AFFECTED: XR Models

MACHINE SYMPTOMS: None

SCOPE OF BULLETIN: Tank warping due to heat

MATERIALS REQUIRED:

None

REVISIONS:

We are now installing a metal support bracket on our XR Recovery tanks to prevent warping in the field. Should a tank warp, please contact <u>warranty@rpscorporation.com</u> and we will work with you to install XR Recovery Tank Support Kit - #700-7015D.



(Warping)

(With Support)



Tank Support Kit #700-7015D



PCB-653