



Our walk-behind Magnum and MiniMag scrubbers along with our rider XR and GTX series scrubbers will now be shipping with a new recovery tank feature. We have added a part to control and eliminate the splashing caused by the recovery water being discharged into a full debris laden drain saver. Although this splashing does not affect the performance and only happens with a full drain saver the visibility into the tank and overall appearance was not good. Installation of the part on older models takes under a minute and requires no tools.



Discharge water in a full drain saver resulting in difficulty viewing inside the tank.



The new part simply slips onto the hose and eliminates the splashing and debris from being thrown onto the clear lid.



The part number is **370-1129**